




NC soft for Machine Shop

Home Page <http://www.autonc.jp>

The Corner Plane Cut Manual



When you machine a steel block on the angle table or on the angle block, this software is used.

[Japanese]


When pushing this button, it becomes Japanese display.

[Parameter]

You specify an editor for the editing.

You start up the editor at the "EDIT" button of the program.

At present, you aren't using the rapid move speed of the machine tool.



[RADIUS]

CORNER CUT RADIUS TOOL

CORNER CUT RADIUS

ラジウス工具

A. Diameter:	<input type="text" value="50"/>	mm
B. Corner R	<input type="text" value="8"/>	mm
Feed Rate:	<input type="text" value="1000"/>	mm/min
Spindle Speed:	<input type="text" value="1200"/>	rev/min
D. Z Down Value:	<input type="text" value="1"/>	mm
E. Std. Cutting Width:	<input type="text" value="25"/>	mm
F. Limit Cutting Width:	<input type="text" value="40"/>	mm
G. Remainder:	<input type="text" value="0"/>	mm
H. Distance X:	<input type="text" value="10"/>	mm

1way
 2way

G92
 Yes
 No

I. Rapid Move Height	<input type="text" value="30"/>	mm
J. Angle(+)	<input type="text" value="55"/>	mm
K. Start Height	<input type="text" value="0"/>	mm
K. End Height	<input type="text" value="-50"/>	mm
L. Y Start Point	<input type="text" value="100"/>	mm
M. Y End Point	<input type="text" value="0"/>	mm

Write Holder: SELECT

Check File: EDIT

File Name: EDIT

NC CHECK
NC DISPLAY
START
CANCEL

Data Area

I. Rapid Move Height	30	mm
J. Angle(+)	55	mm
K. Start Height	0	mm
K. End Height	-50	mm
L. Y Start Point	100	mm
M. Y End Point	0	mm



It makes a corner X0Z0.
And it enters data.

You enter angle in the range of 0 to 90. ($0 < J.Angle < 90$)
It becomes an angle ($90 - angle$) in opposite side.
When it is not below the decimal point, the decimal point can be omitted.

The Y axis data moves from Y Start Point to Y End Point by one-way cut or two-way cut (the range with same Z height).
The starting point of the Y axis is optional.
When it is not below the decimal point, the decimal point can be omitted.

It makes a NC data in the range from Start-Height to End-Height.
Enter Start-Height and End-Height.


For example, it is possible to do the machining of addition when putting from 0 to -30 in the 1st machining and putting from -30 to -50 in the 2nd machining.



Even if it uses the same angle block, with the direction to set, the angle changes.

First, you bring a turning center to the upper left and set the block horizontal. (Angle 0)
 After that, the angle that lowered the right becomes J. angle (+).

(The side with the angle that is more minor gets wide from centerline.)



When measuring a distance from the corner beforehand at the angle block, the position of X0Z0 becomes easy to let out from the result of "the angle calculation".

When the precision isn't necessary
 You turn a tool and set a tool center to the corner by the X-direction.
 And you go down a tool to the point of a blade hit a corner.
 You set to X0Z0.

Cutting Condition

ラジアス工具

A. Diameter: 50 mm
 B. Corner R: 8 mm
 Feed Rate: 1000 mm/min
 Spindle Speed: 1200 rev/min
 D. Z Down Value: 1 mm
 E. Std. Cutting Width: 25 mm
 F. Limit Cutting Width: 40 mm
 G. Remainder: 0 mm
 H. Distance X: 10 mm

<The thinking way of cutting width>

D.Z Down Value, every time it goes down, the width to cut is computed.

The width of cuts is to the position which cutter R comes off touch with block from the position that touches the block.
 (If you input 0 in H, and computes and display in the XZ plane, you understand.)

It cuts off a quotient with (the width / E. Std.cutting width) and it decides the cut number of times.

If it doesn't exceed F.Limit cutting width, it moves a tool at the pace.

When exceeding a F.width, it divides by the cut number of times +1 once more and it decides a pace.

H. When moving Z by rapid move, it takes a distance of this width from steel block.
 (Refer to Data Area picture)

G.Remainder is the remaining finish value.
 (As for general, it assumes 0.)

NC Output

You choose one-way or two-way with the radio button.

When choosing one-way, it moves from the Y start point only to the direction of the Y end point.

When returning to the Y start point, Z rises to the rapid moving height, and moves a pitch after returning to the previous starting-point.

You choose Yes or No at the <G92>.

When you choose Yes, G90G92X0Y0Z(the rapid move z height) is stored.

When it is No, G90X0Y0; G01Z(the rapid move z height) is stored.

(For the details, you refer to the NC data).

"Select" At the button, it selects a write folder.

You enter a file name.
The "Check file" simulates NC movement before actual NC data and confirms data inputs.
" Edit " When pushing the button, the editor starts up and opens a file.


It is possible to display the NC data.

When pushing the "Start" button after fill in all data, the NC data of the file name is created in folder.


When pushing the "Cancel" button, it ends.
Input data is saved and is restored in the next time.

The Display of the NC data


The following shows by "NC DISPLAY" button. This figure is shown in "the XZ plane".




Following figure is shown in "VIEW2".



The following is the figure that was displayed with “Circle” being off.



The following figure is displaying a “Check File”.
You can understand a width of cuts and a shape.



The Display menu



You can select the display direction.

XY plane , XZ plane ,YZ plane, View1, View1a, View2, View3, View3a, View4.

View* is the show which was seen from the diagonal top.

View1, View2, View3, View4 are the show which was seen from 30 degrees above from just beside.

View1a, View3a are the show which was seen from 60 degrees above from just beside.

The show button of Grid, the centerline, the Axis, Circle becomes on.

When making "Grid" off, the grid of blue 50 mm disappears.

When making "Centerline" off, the olive-green X axis, the Y axis, the Z axis disappear.

When making "Axis" off, the coordinate system of the X, the Y, Z disappears.


When making "Circle" off, the tool diameter display disappears.

The part can be displayed in the expansion when clicking with the mouse and dragging.

It returns to the ex-screen by "Close".


[CALCULATE]

For the first time or when pushing the "CLEAR" button, this figure is displayed.



The following figure is displayed when inputting a positive value to the light-blue space and pushing the "CALCULATE" button.

The area of green below becomes the right at the time of + and at the time of -, it becomes the left side.



The above